
**Methods for the calibration of
vibration and shock transducers —**

Part 32:

**Resonance testing — Testing the
frequency and the phase response of
accelerometers by means of shock
excitation**

*Méthodes pour l'étalonnage des transducteurs de vibrations et de
chocs —*

*Partie 32: Essais de résonance — Essai de la fréquence et de la
réponse de phase des accéléromètres au moyen d'excitations par chocs*



COPYRIGHT PROTECTED DOCUMENT

© ISO 2016, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Ch. de Blandonnet 8 • CP 401
CH-1214 Vernier, Geneva, Switzerland
Tel. +41 22 749 01 11
Fax +41 22 749 09 47
copyright@iso.org
www.iso.org

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Factors influencing measurement reproducibility	1
4 Apparatus and other devices	2
4.1 Environmental conditions	2
4.2 Reference shock ball	2
4.2.1 General	2
4.2.2 Reference shock ball dimensions	2
4.2.3 Options for the reference shock ball diameter range	2
4.2.4 Requirements for the mounting surface and the thread tolerances of a reference shock ball	4
4.3 Impact ball	4
4.4 Signal analyser	4
4.5 Conditioning amplifier	5
4.6 Auxiliary devices and means	5
5 Procedure	6
5.1 Assembling the structure under test	6
5.1.1 Mounting the accelerometer under test	6
5.1.2 Mounting a reference shock ball	6
5.1.3 Mounting the guidance tube for the impact ball	6
5.2 Connecting the instruments	7
5.3 Setting the signal analyser	7
5.3.1 Initializing the analyser	7
5.3.2 Specifying the measurement parameters	8
5.3.3 Configuring the display	8
5.3.4 Configuring the markers	8
5.4 Testing	8
6 Processing the results	9
6.1 Recording the time signal	9
6.2 Processing the time signal	9
7 Reporting the results	10
7.1 Reporting the measurement results	10

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see www.iso.org/directives).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see www.iso.org/patents).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation on the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the World Trade Organization (WTO) principles in the Technical Barriers to Trade (TBT) see the following URL: www.iso.org/iso/foreword.html.

The committee responsible for this document is ISO/TC 108, *Mechanical vibration, shock and condition monitoring*, Subcommittee SC 3, *Use and calibration of vibration and shock measuring instruments*.

This first edition of ISO 16063-32 cancels and replaces the first edition of ISO 5347-14:1993, which has been technically revised.

ISO 16063 consists of the following parts, under the general title *Methods for the calibration of vibration and shock transducers*:

- *Part 1: Basic concepts*
- *Part 11: Primary vibration calibration by laser interferometry*
- *Part 12: Primary vibration calibration by the reciprocity method*
- *Part 13: Primary shock calibration using laser interferometry*
- *Part 15: Primary angular vibration calibration by laser interferometry*
- *Part 16: Calibration by Earth's gravitation*
- *Part 17: Primary calibration by centrifuge*
- *Part 21: Vibration calibration by comparison to a reference transducer*
- *Part 22: Shock calibration by comparison to a reference transducer*
- *Part 31: Testing of transverse vibration sensitivity*
- *Part 32: Resonance testing — Testing the frequency and the phase response of accelerometers by means of shock excitation*
- *Part 41: Calibration of laser vibrometers*
- *Part 42: Calibration of seismometers with high accuracy using acceleration of gravity*

— *Part 43: Calibration of accelerometers by model-based parameter identification*

The following parts are under preparation:

— *Part 33: Testing of magnetic field sensitivity*

Methods for the calibration of vibration and shock transducers —

Part 32:

Resonance testing — Testing the frequency and the phase response of accelerometers by means of shock excitation

1 Scope

This part of ISO 16063 lays down detailed specification for instruments and procedures of testing the frequency and the phase response of accelerometers by means of shock excitation. It applies to the accelerometers of the piezoelectric, piezoresistive and variable capacitance types with the damping ratio less than critical and in the frequency range up to 150 kHz.

The method presumes that the frequency and the phase responses of the accelerometer under test gained by this method are the best possible characteristics for the mounted accelerometer on the condition that the recommendations for mechanical mounting of accelerometer stated in ISO 5348 are fulfilled and that the mass of the reference shock ball exceeds at least three times the mass of the accelerometer under test.

Phase response of the accelerometer under test gained by this method is considered to be some “virtual” characteristic of accelerometer presuming that there is zero phase shift between the input and output signals at a frequency of 0 Hz.

NOTE 1 It is intended that the user be aware that for the same accelerometer in the field application, the frequency and the phase responses might be different, depending on the mass and compliance of the test structure and the method of mounting. The method allows just a qualitative evaluation of the frequency and the phase response of accelerometers.

NOTE 2 It is intended that the user does not try to get better resolution of the initial parts of the frequency and phase responses of the accelerometer under test than the dynamic range of the adequate characteristic provides it. The best use of the frequency and the phase responses of the accelerometer gained by this method are to get the best fit lines for the initial parts of the mentioned characteristics.

2 Normative references

The following documents, in whole or in part, are normatively referenced in this document and are indispensable for its application. For dated references, only the edition cited applies. For updated references, the latest edition of the referenced document (including any amendments) applies.

ISO 2041, *Mechanical vibration, shock and condition monitoring — Vocabulary*

ISO 5347-22, *Methods for the calibration of vibration and shock pick-ups — Part 22: Accelerometer resonance testing — General methods*

ISO 5348, *Mechanical vibration and shock — Mechanical mounting of accelerometers*

3 Factors influencing measurement reproducibility

The limits of the uncertainty of the frequency response measurement shall be as follows.

For the resonance frequency of the accelerometer under test, the absolute uncertainty is equal to the frequency analysis resolution and is an inverse value relative to the time-record length of the